
Simplified Adjustments (Z Axis Feed Screw)

Standard Type - Standard Handle / Large Handle / M6 Mounting Holes



There's more on the web: misumiusa.com


Simplified Adjustments (Z Axis Feed Screw)


Standard Type - Standard Handle / Large Handle / M6 Mounting Holes, continued

Part N	Part Number		Travel Distance			-		Р	x	d1	d2	Ł	Load Capacity (N)		Weight
Туре	No.	(mm)	(mm)	Α	L	Z	В	r	^	aı	uz	·	Horizontal	Vertical	(kg)
XKNEJ XKJL	20	20 x 20	±7	20	66	8	20	8	51	3.2	6	2.3	19.6	9.8	0.04
	25	25 x 25		25	71		25	11	56	3.5		3.2			0.05
	40	40 x 40	±9 ±17	40	90	10	40	40	75	4.5	7.5	4.2	39.2	19.6	0.10
	40A	40 x 25				17.5	25	18							0.10
	60	60 x 60	±13 ±23 ±13		120	15	60	30	105						0.18
	60A	60 x 40				25	40								0.15
XKJM XKJML	60	60 x 60		60		15	60								0.18

Travel per rotation 0.7 mm












Alterations		Change of Clamp (Knurled Knob)						
Code		CLC						
Spec.	Mounts a scaled plate to the stage. Minimum Graduation: 0.5 mm The accessory screws will be changed as shown below right. Material: 6063 Aluminum Alloy Surface Treatment: Black Anodize	P ₁ P ₁ D D D D D D D D D D D D D	No. P 20 20 25 3 40 (A) 50	hole pitch to the stage P1 P2 P26 8 B1 11 B0 18 P5 30 B: (4 Pcs.)	since a	d ₂ 4.3 6.0 7.5 7.5	\$	Changes Clamp Screw to Knurled Knob



Conveyor width adjustments during setup changes

